

PRODUCT CHANGE NOTICE

Document ref:	PCN120921A v1.0
Issued:	21 Sep 12
Authorised:	JPG

Products affected

MS3V

Description

The cap of the existing MS3V part was plated with a Gold flash. In the flow of continuous improvement of our product, several different coating materials have been evaluated. Extensive tests have shown that Palladium (Pd) coated surfaces have a superior behaviour concerning solderability over the present cap flash surface.



Original plating (Au)



Replacement plating (Pd)

Transition

The new surface coating with Palladium has been proven to be equivalent or even superior to the Gold plated surface, so transition should be seamless. Supply of Palladium coated parts will commence in the coming months, once stocks of the original gold-plated parts are depleted. Golledge part numbers will not be changing. No customer action is required.

If you require samples for approval or have any queries, please contact your Account Manager or sales@golledge.com